

# Brake Failure from Residual Magnetism in the Mars Exploration Rover Lander Petal Actuator

Louise Jandura\*

## Abstract

In January 2004, two Mars Exploration Rover spacecraft arrived at Mars. Each safely delivered an identical rover to the Martian surface in a tetrahedral lander encased in airbags. Upon landing, the airbags deflated and three Lander Petal Actuators opened the three deployable Lander side petals enabling the rover to exit the Lander. Approximately nine weeks prior to the scheduled launch of the first spacecraft, one of these mission-critical Lander Petal Actuators exhibited a brake stuck-open failure during its final flight stow at Kennedy Space Center. Residual magnetism was the definitive conclusion from the failure investigation. Although residual magnetism was recognized as an issue in the design, the lack of an appropriately specified lower bound on brake drop-out voltage inhibited the discovery of this problem earlier in the program. In addition, the brakes had more unit-to-unit variation in drop-out voltage than expected, likely due to a larger than expected variation in the magnetic properties of the 15-5 PH stainless steel brake plates. Failure analysis and subsequent rework of two other Lander Petal Actuators with marginal brakes was completed in three weeks, causing no impact to the launch date.

## Introduction

Two Mars Exploration Rover (MER) spacecraft were sent to Mars, each with a rover to explore the Martian surface with its suite of instruments. After entering the Martian atmosphere in an aeroshell, the rovers were delivered to the surface in a Lander covered in airbags. Once the landing system came to rest on the Martian surface and the airbags deflated, three Lander Petal Actuators (LPAs) opened the three deployable Lander side petals, enabling the rover to exit the Lander. Approximately nine weeks prior to the scheduled launch of the first spacecraft, one LPA exhibited a brake failure during its final flight stow at Kennedy Space Center. The failure analysis of this mission critical actuator and the subsequent rework of two other marginal flight LPAs were all done without causing the launch date to slip.


The MER spacecraft, carrying the rovers called Spirit and Opportunity, were launched on June 10, 2003 and July 7, 2003. These spacecraft successfully landed on Mars on January 3, 2004 and January 24, 2004 respectively. All six LPAs operated without any problems.

Figures 1 and 2 show the LPAs installed in the Lander in both the stowed and deployed configurations. The tetrahedral Lander shape with its three LPA-deployed side petals is inherited from the 1997 Mars Pathfinder (MPF) program [1]. With this arrangement, the Lander can right itself from any side petal onto its base petal by opening that side petal until the Lander center of gravity tips the entire system onto the base petal. The LPA torque requirements for MER were much higher due primarily to the larger mass of the landed system, making a re-flight of the MPF LPA design impossible. The same MPF volume constraints for the LPA were applied to MER so the Lander would fit inside the aeroshell. Maintaining the same volume and nearly the same mass as MPF while producing three times the output torque was a significant challenge for the MER LPA. Each LPA had to develop sufficient torque to lift, overturn and right the Lander should it come to rest on a side petal rather than the base petal. Both the first MER lander and the MPF lander stopped on the base petal. However, the second MER lander came to rest on a side petal, causing that side petal LPA to right the lander. In addition, each LPA had to be able to over-deploy its petal to assist in leveling the Lander for a safe rover egress should it come to rest on uneven terrain. Thus, the actuator's unpowered holding torque (or backdrive torque) had to exceed the reaction load from the weight of the Lander supported on a petal with that petal in the fully deployed position. Petal adjustments were made on each MER lander to aid the rover egress. During petal opening, LPA position


---

\* Jet Propulsion Laboratory, California Institute of Technology, Pasadena, CA

knowledge is provided by an incremental encoder signal constructed in the LPA electronics from the motor commutation sensor signals. The LPA electronics are brushless motor drive electronics, physically



**Figure 1. Lander Petal Actuators open each MER Lander side petal to the iron cross position, where all petals are coplanar. Petal motion past this condition is called over-deployed.**



**Lander Petal Actuator**

**Lander Petal Actuator**

**Figure 2. The MER Lander with two side petals stowed and the third side petal closing under the action of its Lander Petal Actuator**




Figure 3. MER Lander Petal Actuator with its electronics




Figure 4. The LPA motor and brake are separately powered and commanded by the system electronics through the LPA electronics, a brushless motor drive electronics.

separate from the LPA and connected by a cable (Figure 3). Potentiometers at each of the petal hinge lines provide additional coarse petal position information, an absolute reference for rover egress.

#### Lander Petal Actuator

The MER Lander Petal Actuator (Figure 3) is a high torque actuator (3300 N•m output torque) produced by Aeroflex Laboratories, Inc., which consists of a brushless DC motor, a power-off brake, 7 stages of planetary gearing with an overall ratio of 324,099:1, and a crowned spline on the output shaft. The LPA required a brake to meet its backdrive torque requirements with power removed because of the high efficiency of the planetary gearing. The brake is mechanically engaged when non-powered to lock the motor rotor and ensure that the Lander petals cannot move due to external loads. The LPA motor and LPA brake are separately powered and commanded by the system electronics through the LPA electronics (Figure 4). During operation, power is first applied to the LPA brake to release it, followed by

power to the LPA motor to initiate petal motion. At the conclusion of motion, power is first removed from the LPA motor and then the LPA brake to avoid clamping the brake rotor at high speed. All LPAs were tested over temperature at the actuator level to restrain 3300 N•m externally applied to the output shaft. The brake design is a standard spring-applied, power-to-release configuration as shown in the motor/brake assembly cross-section (Figure 5). The brake rotor is attached to the motor rotor. With the brake unpowered, 6 compression springs push the friction plate against the brake rotor, preventing motor rotation. When the brake is energized to release the motor, the friction plate is guided on 3 pins and pulled against the springs by the solenoid. The total stroke of the friction plate is 0.13 mm. There is a 0.051 mm annular non-magnetic shim between the friction plate and the solenoid to break the magnetic flux path and prevent residual magnetism from permanently retaining the friction plate on the solenoid (the stuck-open position).





Figure 5. Cross-section of the Lander Petal Actuator motor/brake assembly

### Failure and Failure Investigation

The LPA failure occurred about nine weeks before the scheduled launch of the first MER spacecraft. In preparation for closing the Lander for the last time, the spacecraft commanded the Lander petals through their range of motion using the LPAs so that cabling and other hardware near the hinge line could be observed for proper installation and clearance. Although the petals had been moved with the LPAs many times before, this was the first time that all the hardware including the flight airbags was installed during the motion. During a pause in the final flight stow sequence of the Lander petals using the LPAs, one petal drifted downward under gravity with the spacecraft unpowered. The weight of the assembled petal applied about 418 N•m of torque to the LPA output shaft or 13% of the tested backdrive resistance. A load of this magnitude clearly should not have caused the actuator to backdrive with the brake engaged. The failure was initially observed visually as an offset between the commanded position and the actual position. One petal seemed lower than it should be. A check of spacecraft telemetry from the hinge line potentiometers indicated that there was continued motion after completion of the commanded motion, on one petal only, although the current draw from the brake was as expected during the motion and went to zero upon completion of the motion. Once a problem was suspected, the continued motion was also visually observed. The anomaly was repeatable. In a separate check, the suspect petal moved when the LPA was commanded without energizing the brake, a further sign that the brake was not performing properly.

Even though all evidence pointed toward a problem with the LPA brake, a brake failure did not seem credible. Swift, decisive action was required to prevent a launch delay, however the closeness to launch made it even more critical to conclusively isolate the problem prior to removing the hardware from the spacecraft. Uncertainty in determining the cause of the problem would jeopardize the launch. The problem was conclusively isolated to the actuator using the following rationale. With the petal backdriving, the spacecraft was powered off and the connectors between the spacecraft, the LPA drive electronics, and the LPA were demated sequentially until the LPA was completely isolated from the rest of the system. The petal was still backdriving, which conclusively placed the failure in the actuator, eliminating the possibility that a stray current in the system or the drive electronics was keeping the brake powered and in the open position. The failed LPA (SN 007) was removed from the Lander and replaced by a flight spare and failure analysis began on the removed LPA. The failure investigation was conducted at Kennedy Space Center to eliminate the possibility that the failure would be lost during transportation of the LPA to either the Jet Propulsion Laboratory or Aeroflex Laboratories, Inc.



**Figure 6. Fault tree for LPA brake failure with the actual failure highlighted in the dotted box**

The evidence at this point only indicated that the brake was not resisting motion. Many different failure possibilities were considered which fell into the following general categories: “Brake in Open Condition”; “Loss of Friction at Brake Interface”; or “Rotor Not Transmitting Torque to Brake Assembly” (Figure 6). Many of the failures could only be observed through disassembly of the brake and some of these had the additional unfortunate characteristic that disassembly could cause the loss of the failure. After visual examination of the LPA indicated nothing unusual, the motor was operated with no power to the brake. Motor current indicated no-load operation, which meant the failure was still intact. Real time X-ray examination revealed the brake in a fully disengaged position even though no power was applied to the

brake. This observation eliminated two of the three branches of the fault tree, leaving only the failures listed under “Brake in Open Condition”. No tilting of the friction plate was apparent and nothing unusual was observed in the brake assembly. The only failure remaining that could be determined without disassembly was “Residual Magnetic Field Holding Brake Open”. While still under X-ray examination, a reverse polarity voltage was slowly applied to the brake starting at 0 volts, a demagnetizing action for the friction plate. At negative 0.3 volts, the friction plate moved to the engaged position against the motor rotor indicating the failure was caused by residual magnetism holding the friction plate against the solenoid even though a non-magnetic washer was in the assembly to prevent this particular failure. The motor stalled when operated again with the brake unpowered proving that the demagnetized brake was now fully mechanically engaged. Residual magnetism was the source of the failure in this LPA!

### Assessment of Other LPAs

A survey of the acceptance test data for all LPA brake assemblies was performed as a consequence of the SN 007 LPA brake failure. Particular attention was given to the pull-in and drop-out voltages for the brake assemblies since these measurements are an indication of the electromechanical performance of the units. With no voltage applied to the brake, the friction plate is pressed against the brake rotor by the compression springs. Pull-in voltage is measured by slowly raising the brake voltage from zero volts until the friction plate is pulled in to the solenoid, mechanically disengaging from the brake rotor and permitting the motor to turn when the motor is powered with its drive electronics. Figure 7 illustrates the force balance for pull-in. Increasing the voltage across the brake coil causes the current in the solenoid to increase. As the current increases, the magnitude of the magnetic field increases thereby increasing the magnetic force,  $F_M$ , on the friction plate. The two forces that act in opposition to  $F_M$  are  $F_S$ , the total force from the 6 compression springs, and  $F_f$ , the friction force between the 3 guide pins and the friction plate. When the magnetic force exceeds the sum of the spring and friction forces, or

$$F_M > F_S + F_f \tag{1}$$

the friction plate moves away from the brake rotor and toward the solenoid, mechanically disengaging the brake. Once motion starts, the brake plate moves quickly open since  $F_M$  increases much faster than  $F_S$  as the air gap decreases.  $F_M$  is a squared function of air gap while  $F_S$  is a linear function.




Figure 7. Force balance for brake pull-in and drop-out voltages

Drop-out voltage is then measured by slowly lowering the voltage until the friction plate releases from the solenoid, mechanically engaging the brake rotor again. Figure 7 illustrates the force balance for drop-out. Decreasing the voltage across the solenoid reduces its current and therefore the magnitude of the

magnetic field. As a result,  $F_M$  decreases. When the total spring force is sufficient to overcome both the magnetic force and the friction force, or

$$F_S > F_M + F_f \quad (2)$$

the friction plate moves away from the solenoid and reengages the brake rotor. Once motion begins, the friction plate moves quickly to the engaged position since  $F_M$  decreases much faster than  $F_S$  as the air gap increases. In the case of the failed brake, the condition in equation 2 was not met even though the solenoid voltage and therefore current was zero.  $F_M$  was non-zero due to residual magnetism.

The pull-in and drop-out motions of the brake are critical to the operation of the LPA and must be assessed for force margin like any other critical deployment. The desire was to have a force capability of at least twice the force needed to move the components over all conditions of environment and operating voltage. This equates to a minimum factor of safety (the ratio of force capability to force required) of 2.0. The flight brakes were measured to have a pull-in voltage <17 VDC, demonstrating operating margin from the minimum flight input voltage of 24 VDC. The magnetic force is 20 N at 17 VDC and 37.6 N at 24 VDC compared to a maximum total spring force of 10.45 N and an analytically determined maximum friction force of 0.013 N, surpassing the minimum desired force factor of safety for the pull-in deployment by a large amount. Drop-out voltage was measured to be <10 VDC, ensuring adequate separation between the pull-in and drop-out behavior. However no lower threshold on drop-out voltage was defined to ensure operating margin above zero input voltage. The lack of an appropriately specified lower bound for this parameter was an oversight that hindered the discovery of brakes with insufficient force margin for drop-out during acceptance testing. The minimum required force factor of safety for the drop-out deployment was not proven during acceptance testing. Since the failed LPA clearly did not have sufficient margin for drop-out, the other flight LPAs, which were already installed on the flight Landers, were evaluated. The pull-in and drop-out voltages of all LPA brakes were recorded during acceptance testing and measured again after the failure (Table 1). Although the failed unit had the lowest measured value of drop-out voltage, SN 003 and 008 also had very low values for drop-out voltage, raising suspicions that these two actuators might also have insufficient margin for drop-out. A proper specification of drop-out voltage defining sufficient force margin was needed to properly evaluate the flight LPAs and determine if rework was required. LPAs were switched between the two landers, placing the three flight LPAs with the highest values of drop-out voltage on the first lander being prepared for launch. This allowed preparations to continue on the most time-critical lander while the LPA assessment continued, maximizing the chance that the failure could be addressed without impacting either launch.

**Table 1. LPA Pull-In and Drop-Out Voltage Measurements**

SN ( <sup>a</sup> )Failed Unit	Acceptance Test Values (VDC)		As Remeasured (VDC)		Type of Unit
	Pull-In	Drop-Out	Pull-In	Drop-Out	
001	14.1	2.2	12.3	2.22	Qualification
002	Not avail.	Not avail.	12.9	3.25	Flight
003	14.3	1.9	13.6	0.79	Flight
004	12.0	5.0	15.9	3.79	Flight
005	15.5	1.0	Not meas.	Not meas.	Testbed
006	14.07	2.6	14.1	2.40	Flight
007( <sup>a</sup> )	12.7	0.6	12.8	-0.3, 0.29	Flight
008	13.7	1.1	11.7	1.25	Flight
009	12.8	1.72	12.2	1.02	Testbed
010	15.1	0.85	Not meas.	Not meas.	Testbed
011	13.8	2.3	13.7	2.54	Flight Spare

There is no way to take a direct measurement of force in the brake assembly on the fully assembled LPA, therefore there is no way to directly verify the force margin for drop-out on each LPA. Since drop-out voltage is the only easily acquired measurement on the fully assembled LPA, what was needed was a relationship between drop-out voltage and force so that a minimum force factor of safety of 2.0 could be guaranteed. A series of tests was performed on a spare brake assembly to determine how drop-out

voltage varied with spring force. The nominal spring force was calculated from the spring constant and the geometry of the brake assembly. Starting with the friction plate pulled in against the solenoid, the voltage to the brake was lowered until the plate moved under the force of the springs. Reducing the number of springs in the brake assembly decreased the spring force pushing on the friction plate until the brake plate no longer dropped out at zero voltage (Table 2). At this condition, the residual magnetic force is greater than the spring force attempting to push the brake plate off the solenoid. An additional test was performed with no springs in the brake assembly. The voltage to the brake was reduced to zero and a measurement of the force required to separate the friction plate from the solenoid was recorded (Table 3). The same measurements were taken after adding a second non-magnetic 0.051 mm shim between the solenoid and the friction plate (Tables 2 and 3). Adding the second shim raised the drop-out voltage significantly (Figure 8) without changing the pull-in voltage substantially. These tests enabled a method to determine the force margin and illustrated a rework path that could increase that margin.

**Table 2. Drop-out voltage vs. spring force as measured on a spare brake**

# of Springs	0.051-mm shim		2x 0.051-mm shim	
	Nominal Force (N)	Voltage (V)	Nominal Force (N)	Voltage (V)
6	9.012	1.27	8.910	3.60
5	7.508	0.92	7.428	3.21
4	6.005	0.22	5.943	2.12
3	4.506	No release <sup>(b)</sup>	4.457	1.51
2			2.971	0.35
1			1.486	No release

<sup>(b)</sup>No release at zero volts, released with -0.3 volts (reverse polarity voltage of 0.3 volts)

**Table 3. Force required to separate the friction plate from the solenoid at zero volts as measured on a spare brake**

# of Springs	0.051-mm shim		2x 0.051-mm shim	
	Nominal Force (N)	Voltage (V)	Nominal Force (N)	Voltage (V)
0	4.706	0	2.224	0

The required margin point for each shim condition was determined using the spring force test data and a tolerance analysis of spring force. A quadratic equation was fit to the test data in Figure 8 since force in the solenoid is a quadratic function of current and therefore voltage. Regression results in equations of the form:

$$F_M = aV^2 + bV + c \quad (3)$$

with  $a$ ,  $b$ , and  $c$  all constants. Setting  $c$  equal to the minimum possible spring force of three springs minus the maximum possible friction force from the alignment pins shifted the curves. This ensures that when six springs are present, there is a minimum factor of safety of 2.0 on the force required to create drop-out at the zero voltage condition. The two shifted regression curves are plotted in Figure 9, one curve for a single, non-magnetic 0.051-mm shim and one for a double, non-magnetic shim or a 0.102 mm total shim thickness. The final margin point for each shim thickness was calculated from the regression curves as the drop-out voltage values corresponding to the maximum possible force from 6 springs plus an additional two times the friction force. An additional 0.1 VDC was added to account for measurement scatter resulting in required minimum drop-out voltage values of 2.05 VDC for the 0.051-mm shim thickness and 3.81 VDC for the 0.102-mm shim thickness. It should be noted that the drop-out voltage of 0.6 measured during acceptance testing of the failed LPA works out to a force factor of safety of 0.97. This was a unit that clearly should have failed.




Figure 8. Test data from a spare brake assembly characterizes the variation of drop-out voltage with spring force for two different shim thicknesses.




Figure 9. Regression curves from test data are appropriately shifted and used to determine the drop-out voltage required for a minimum 2.0 factor of safety.